

iMac Intel 21.5" EMC 2428 Audio Ports Replacement

Prereq only.

Written By: Walter Galan



This document was generated on 2020-11-28 02:19:31 AM (MST).

INTRODUCTION


Prereq only.



TOOLS:

• T10 Torx Screwdriver (1)

Step 1 — Audio Ports



 Remove the two 5 mm T10 Torx screws securing the audio ports to the outer case.

Step 2





- Press both audio ports down slightly, then lift the audio port assembly out of the outer case.
- A pair of tweezers is helpful to put the ports back in place. First insert the lower tab into the bracket on the outer case, then fasten the screw to secure the jack to the outer case.
- During reinstallation, it may be helpful to plug in a pair of headphones to each jack before tightening them down completely.

To reassemble your device, follow these instructions in reverse order.